

CII National Award For Environmental Best Practices-2023

Presenter -

Mr. Mahatab Raza

Mrs. Ruchi Wagadre

Mr. Manas Majumdar

21.06.2023

ReCon India DTA – Overview	
Name:	New & ReCon Parts – DTA Phaltan
Established in:	February 2011
Location:	Phaltan, Maharashtra
Product Families :	1. Cylinder head 2. PT Fuel Injector 3. PT Fuel pump 4. Cam follower 5. Filter Head
Total area:	4635 Sqm (2072 Sqm ReCon DTA ; 2563 Sqm CES)
Total headcount:	Total: 129 On Roll: 98 (Including Trainees/Apprentice/Interns/FTC) Off Roll: 31 Exempt: 5, Office: 3 Shop: 45, Apprentice: 13, FTC 32, House Keeping 8, Securtity 7, Garden 2, Canteen 2, Material Handling 9, ETP 2.CWK-1
Gender diversity:	34%
Key customers:	HHP Rebuild Center, India Parts Distribution Center and Kothrud Engine Plant
Certifications	ISO 14001:2015; ISO 45001:2018 for HSEMS ISO 9001: 2015 for Quality Management System GreenCo Gold in 2018 and Platinum in 2019 NAMC Gold Certification in 2019 for Manufacturing Competitiveness





Plant Achievements

- BIS PPM sustenance for 65 consecutive months
- NRPO Won Winner "Sustained Commitment to AMaZe 2.0 Excellence Journey" (ISCM Awards)
- CII Gold and Silver Recognitions for Plant.


Cummins 2





Reuse of Discarded Cyl Head By Developing Defect Removal Process Trigger – Higher rejection of cylinder head Pitting Defect on Injector bore Dent on Injector Bore


Cummins | 4


4




















Achieving national benchmarks/Standards

Benchmarked this micromachining process in the remanufacturing standards where other remanufacturing plants can implement the same when similar issue arises.

Cummins | 13

13

Priority plans on fast track for +1 year and +2 year, including resource requirement

- Defect Exhaust face gasket impression
- · Salvage Welding

- Defect Exhaust face gasket impression
- Salvage Welding

- Defect Below DDL Specification
- · Salvage Thermal spray

- Defect Side expansion plug bore pitting and damage
- Salvage Threaded plug

- Defect Coating wear out, tapper
- Salvage Plunger de-coating & coating

- Defect Pitting in Adaptor & Retainer
- Salvage Visual inspection with engine test & Performance

Cummins | 14

Top Ten Best Practices

Cummins | 15

Waste Management



15

Zero Waste Disposal
100% recycling of waste



■ Environmentally friendly processes

Burn-off process instead of chemical cleaning process



Returnable packaging

Returnable skids, reuse of packaging material



Sustainable materials

Biodegradable chemicals





Filtration




Elimination of primary chemical cleaning machine

Chemical cleaning replaced with burn off process leading to significant amount of chemical reduction

Recirculation of chemical for cleaning

More than 50% of chemical recirculated after introducing a filtration unit.

Fresh chemical consumption and waste chemical disposal drastically reduced.



17

Water Conservation



Water Neutral

1: 13 water generation for communities as compared to water used for the plant



Water reduction

Waterless urinals Low flow faucets




Water recycling

Component cleaning



Rainwater harvesting

Groundwater recharge Reuse for domestic purpose



Green Supply Chain



Supplier & vendor management

i-supplier portal Supplier conference



Green procurement

Cardboard made from recycled material Recycled plastic packaging EPR




Milk runs

Transportation management system Local supplier identification



Returnable packaging

Build to ship to packaging Returnable skids



19

